


REPLACEMENT PARTS FOR WS275A STUD WELDER STARTER KIT



ITEM #	DESCRIPTION	Part Number	QTY
	COMPLETE REPLACEMENT WELDER	WS55090	1
1	TRANSFORMER	4514	1
2	HOUSING	4509	1
3	POWER CABLE	4523	1
4	TRIGGER SWITCH	4515	1
5	OVERLOAD RELAY	4521	1
6	FIBER HEAD ASSEMBLY WITH STUD EASE	4510	1
6a	FIBER HEAD	4511	1
6b	ELECTRODE WITH STUD EASE AND HARDWARE (NO SWT1004)	1012-02	1
6c	ELECTRODE SPRING	1022	1
6d	GROUND RING	1013	1
7	STUD WELDING TIP (NOT INCLUDED WITH WS55090 GUN)	WS1104	1
Not Shown	HEX KEY CAP SCREWS 55mm X 5mm	1090	6
Not Shown	HEX KEY CAP SCREWS 25mm X 5mm	1090-01	2
Not Shown	HEX NUTS 5mm	1090-03	8